



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
03/24/2006

Supervisor 

**Mine Name:** Neilson Sandstone  
**Operator Name:** Ash Grove Cement Company  
**P.O. Box 51**  
**Nephi, Utah 84648**  
**Inspector(s):** Tom Munson  
**Other(s):** Jeff Peterson and Josh Nelson  
**Mine Status:** Active

**Permit number:** M230012  
**Inspection Date:** 03/23/06  
**Time:** 10:30 AM

**Weather:** Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:** To perform an Annual inspection, focusing on storage of Mill Scale from Geneva Steele and the active mining of high silica sandstone.

**Directions to Site:** The site sits west of Nephi on Route 132 East of the town of Leamington.

**Inspection Summary:** I viewed the active compaction of the mill scale imported from Geneva Steel in Orem in Pit 1 as approved by the Division June 14, 2005. It appeared to be well within the boundary of the site and was a little more than half complete.

Next I visited the active mine site or Pit 2 where stockpiled blasted silica was being crushed and stockpiled by a sub contractor for shipment to the plant. This was also within permitted boundaries.

**Conclusions and Recommendations:**

The inspection revealed nothing unusual or out of compliance.

**Inspector's Signature**  **Date:** 3/24/2005

tm:pb

cc: Operator

Attachment: Photos

P:\GROUPS\MINERALS\WP\M023-Juab\M0230012-NielsonSSQuarry\Final\insp03232006.doc






NEILSON SANDSTONE

PIT 2

CRUSHER STRIKE

m/023/012





03.23.2006 11:49

WELSON SANDSTONE  
STOCK PILE MATERIAL  
PIT 2





STOCKPILE OF SANDSTONE

NIELSON SANDSTONE

M023 00 10

PITZ





NIELSON SANDSTONE

M0230010

PIT 2



NELSON SANDSTONE

WATER  
BOYD ARCS

1

1


1

M14

03-23-2006 11:39

DUKE  
CORPORATION  
Tel. 714  
435-623-2332





NEISO SANDSTONE  
PIT 1  
STOCKPILED MILL SCALE  
FROM GENEVA STEEL